STIHL - 42379580500 - Arandela tornillo cuchilla cortasetos STIHL

HS45, HS46, HS46C, HS56C, HS81R, HS81T, HS82R, HS82T, HS86R, HS86T, HS87R, HSA100, HSA130R, HSA130T, HSA140R, HSA140T, HSA150R, HSA150T, HSA60, HSA66, HSA86, HSA94R, HSA94T, HSE42, HSE52, SPA130

Recambio original para las siguientes máquinas STIHL:

FH-KM145° | HL0° | HL145° | HL92C-E | HL94C-E | HL94KC-E | HLA135 | HLA135K | HLA65 | HLA66 | HLA85 | HLA86 | HL-KM0° | HL-KM145° | HS45 | HS452-MIX | HS46 | HS46C-E | HS56C-E | HS81R | HS81T | HS82R | HS82T | HS86R | HS86T | HS87R | HSA100.0 | HSA100.1 | HSA130.0R | HSA130.0T | HSA140.0R | HSA140.0T | HSA150.0R | HSA150.0T | HSA60.0 | HSA60.1 | HSA66 | HSA86 | HSA94R | HSA94T | HSE42 | HSE52 | SPA130.0 | SPA140.0 | SPA65

Tipo de máquina: Cortasetos

Referencias OEM STIHL: 42379580500, 4237 958 0500, 4237-958-0500

Referencias alternativas STIHL:

Denominaciones STIHL: Arandela

Modelo de STIHL: FH-KM 145°, HL 0°, HL 145°, HL 92 C-E, HL 94 C-E, HL 94 KC-E, HLA 135, HLA 135 K, HLA 65, HLA 66, HLA 85, HLA 86, HL-KM 0°, HL-KM 145°, HS 45, HS 45 2-MIX, HS 46, HS 46 C-E, HS 56 C-E, HS 81 R, HS 81 T, HS 82 R, HS 82 T, HS 86 R, HS 86 T, HS 87 R, HSA 100.0, HSA 100.1, HSA 130.0 R, HSA 130.0 T, HSA 140.0 R, HSA 140.0 T, HSA 150.0 R, HSA 150.0 T, HSA 60.0, HSA 60.1, HSA 66, HSA 86, HSA 94 R, HSA 94 T, HSE 42, HSE 52, SPA 130.0, SPA 140.0, SPA 65

Tipo de recambio: Original OEM

Fabricante: STIHL

Medidas:
Exterior: Ø 20 mm
Interior: Ø 5,1 mm
Grosor: 1,2 mm

