

## **STIHL - 41401290900 - Junta admisión de carburador STIHL**

MM55, BG45, BG55, BG85, FC100, FC110, FS100, FS38, FS45, FS55, FS87, FS90, HL100, HL45, HL90K, HL95, HS45, HS81R, HS81T, HS86R, HS86T, HT100, HT101, KM100, KM55, KM90, SH55, SH85, SP90

Recambio original para las siguientes máquinas STIHL:

MM55 | BG45 | BG55 | BG85 | BR45C | BT45-Z | FC100 | FC110 | FS100 | FS100R | FS38 | FS38-Z | FS45 | FS45C-E | FS55 | FS55R | FS55RC-E | FS55T | FS87 | FS87R | FS90-4180 | FS90R-4180 | HL100 | HL100K | HL45 | HL90K | HL95 | HL95K | HS45 | HS81R | HS81T | HS86R | HS86T | HT100 | HT101 | KM100 | KM100R | KM55 | KM55R | KM55RC-E | KM90 | KM90R | SH55 | SH85 | SP90 | SP90T

Tipo de máquina: Cortabordes, Desbrozadora, Soplador, Cortasetos, Motor sistema combinado, Vareador

Referencias OEM STIHL: 41401290900, 4140 129 0900, 4140-129-0900

Denominaciones STIHL: Junta admisión carburador

Modelo de STIHL: MM 55, BG 45, BG 55, BG 85, BR 45 C, BT 45-Z, FC 100, FC 110, FS 100, FS 100 R, FS 38, FS 38-Z, FS 45, FS 45 C-E, FS 55, FS 55 R, FS 55 RC-E, FS 55 T, FS 87, FS 87 R, FS 90 - 4180, FS 90 R - 4180, HL 100, HL 100 K, HL 45, HL 90 K, HL 95, HL 95 K, HS 45, HS 81 R, HS 81 T, HS 86 R, HS 86 T, HT 100, HT 101, KM 100, KM 100 R, KM 55, KM 55 R, KM 55 RC-E, KM 90, KM 90 R, SH 55, SH 85, SP 90, SP 90 T

Tipo de recambio: Original OEM

Fabricante: STIHL

