

STIHL - 63757640601 - Carcasa manillar lado exterior izdo.cortacésped VIKING

MB545.0, MB545.0T, MB545.0V, MB545.0VE, MB545.0VR, MB545.0VS, MB545.1T, MB545.1V, MB545.1VE, MB545.1VR, MB650.0KS, MB650.0T, MB650.0TK, MB650.0V, MB650.0VE, MB650.0VQ, MB650.0VS, MB650.1V, MB655.0G

Recambio original para las siguientes máquinas STIHL:

MB545.0 | MB545.0T | MB545.0V | MB545.0VE | MB545.0VR | MB545.0VS | MB545.1T | MB545.1V | MB545.1VE | MB545.1VR | MB650.0KS | MB650.0T | MB650.0TK | MB650.0V | MB650.0VE | MB650.0VQ | MB650.0VS | MB650.1V | MB655.0G | MB655.0GK | MB655.0GQ | MB655.0KS | MB655.0V | MB655.1G | MB655.1V | MB655.1VR | MB655.1VS | ME545.0 | ME545.0C | ME545.0V

Tipo de máquina: Cortacésped

Referencias OEM STIHL: 63757640601, 6375 764 0601, 6375-764-0601

Referencias alternativas STIHL: 63757640600, 6375 764 0600, 6375-764-0600

Denominaciones STIHL: Mitad de carcasa, Carcasa manillar lado exterior izquierdo, Tapa

Modelo de STIHL: MB 545.0, MB 545.0 T, MB 545.0 V, MB 545.0 VE, MB 545.0 VR, MB 545.0 VS, MB 545.1 T, MB 545.1 V, MB 545.1 VE, MB 545.1 VR, MB 650.0 KS, MB 650.0 T, MB 650.0 TK, MB 650.0 V, MB 650.0 VE, MB 650.0 VQ, MB 650.0 VS, MB 650.1 V, MB 655.0 G, MB 655.0 GK, MB 655.0 GQ, MB 655.0 KS, MB 655.0 V, MB 655.1 G, MB 655.1 V, MB 655.1 VR, MB 655.1 VS, ME 545.0, ME 545.0 C, ME 545.0 V

Tipo de recambio: Original OEM

Fabricante: STIHL

