

STIHL - 00004051007 - Pipa de bujía STIHL

FS94C, FS94RC, HL92C, HL94C, HS46, HS56C, KM94RC, MS192C, MS193C, MS193T, MS194C, MS194T, MS201, MS201C, MS201T, MS231, MS231C, MS241C, MS251, MS251C, MS362C, MS400C, MS462C, SP92C, SP92TC

Recambio original para las siguientes máquinas STIHL:

FS94C-E | FS94RC-E | HL92C-E | HL94C-E | HL94KC-E | HS46 | HS46C-E | HS56C-E | KM94RC-E | MS192C-E | MS193C-E | MS193T | MS193TC-E | MS194C-E | MS194T | MS194TC-E | MS201 | MS201C-M | MS201T | MS201TC-M | MS231 | MS231C-BE | MS241C-M | MS251 | MS251C-BE | MS362C-M | MS400C-M | MS400.1C-M | MS400.1C-MR | MS400.1C-MVW Arctic | MS462C-M | MS462C-MR Rettungssäge | SP92C-E | SP92TC-E

Tipo de máquina: Motosierra, Desbrozadora, Cortasetos, Motor sistema combinado, Vareador

Referencias OEM STIHL: 00004051007, 0000 405 1007, 0000-405-1007

Referencias alternativas STIHL: 00004051004, 0000 405 1004, 0000-405-1004

Denominaciones STIHL: Enchufe de bujía, Pipeta de bujía, Capuchón de bujía

Modelo de STIHL: FS 94 C-E, FS 94 RC-E, HL 92 C-E, HL 94 C-E, HL 94 KC-E, HS 46, HS 46 C-E, HS 56 C-E, KM 94 RC-E, MS 192 C-E, MS 193 C-E, MS 193 T, MS 193 TC-E, MS 194 C-E, MS 194 T, MS 194 TC-E, MS 201, MS 201 C-M, MS 201 T, MS 201 TC-M, MS 231, MS 231 C-BE, MS 241 C-M, MS 251, MS 251 C-BE, MS 362 C-M, MS 400 C-M, MS 400.1 C-M, MS 400.1 C-M R, MS 400.1 C-M VW Arctic, MS 462 C-M, MS 462 C-M R Rettungssäge, SP 92 C-E, SP 92 TC-E

Tipo de recambio: Original OEM

Fabricante: STIHL



