

STIHL - 63757640615 - Carcasa manillar lado interior izdo.cortacésped VIKING

MB545.0, MB545.0T, MB545.0V, MB545.0VR, MB545.0VS, MB545.1T, MB545.1V, MB545.1VR,
MB650.0KS, MB650.0T, MB650.0TK, MB650.0V, MB650.0VQ, MB650.0VS, MB650.1V, MB655.0G,
MB655.0GK, MB655.0GQ, MB655.0KS

Recambio original para las siguientes máquinas VIKING:

MB545.0 | MB545.0T | MB545.0V | MB545.0VR | MB545.0VS | MB545.1T | MB545.1V | MB545.1VR |
MB650.0KS | MB650.0T | MB650.0TK | MB650.0V | MB650.0VQ | MB650.0VS | MB650.1V | MB655.0G |
MB655.0GK | MB655.0GQ | MB655.0KS | MB655.0V | MB655.1G | MB655.1V | MB655.1VR | MB655.1VS |
ME545.0V

Tipo de máquina: Cortacésped

Referencias OEM STIHL: 63757640615, 6375 764 0615, 6375-764-0615

Denominaciones STIHL: Mitad de carcasa, Carcasa manillar lado interior izquierdo, Tapa

Modelo de VIKING: MB 545.0, MB 545.0 T, MB 545.0 V, MB 545.0 VR, MB 545.0 VS, MB 545.1 T, MB
545.1 V, MB 545.1 VR, MB 650.0 KS, MB 650.0 T, MB 650.0 TK, MB 650.0 V, MB 650.0 VQ, MB 650.0
VS, MB 650.1 V, MB 655.0 G, MB 655.0 GK, MB 655.0 GQ, MB 655.0 KS, MB 655.0 V, MB 655.1 G, MB
655.1 V, MB 655.1 VR, MB 655.1 VS, ME 545.0 V

Tipo de recambio: Original OEM

