

STIHL - 95030036841 - RODAMIENTO DE BOLAS 6205-2RS

RT4082.0, RT4082.1, RT4097.0SX, RT4097.1SX, RT5097.0, RT5097.0C, RT5097.0Z, RT5097.1, RT5097.1Z, RT5112.1Z, RT6112.0C, RT6112.0ZL, RT6112.1ZL, RT6127.0ZL, RT6127.1ZL, GH370.0S, GH370.1S, GH460.0C

Recambio original para las siguientes máquinas STIHL y VIKING:

RT4082.0 | RT4082.1 | RT4097.0SX | RT4097.1SX | RT5097.0 | RT5097.0C | RT5097.0Z | RT5097.1 | RT5097.1Z | RT5112.1Z | RT6112.0C | RT6112.0ZL | RT6112.1ZL | RT6127.0ZL | RT6127.1ZL | GH370.0S | GH370.1S | GH460.0C | GH460.1C | MH445.0 | MH445.1 | MR4082.0 | MR4082.0K | MR4082.1 | MR4082.2 | MT4097.0SX | MT4097.1SX | MT4112.0S | MT4112.1S | MT5097.0 | MT5097.0C | MT5097.0G | MT5097.0K | MT5097.0Z | MT5097.1 | MT5097.1C | MT5097.1Z | MT6112.0 | MT6112.0C | MT6112.0K | MT6112.0ZL | MT6112.1C | MT6112.1ZL | MT6127.0KL | MT6127.0ZL | MT6127.1ZL | MT640(1996) | MT640(1997) | MT680 | AMS127 | HB445.0 | HB445.0R | HB445.1 | HB445.1R | HB445.2 | HB445.2R | HB560.0 | HB585.0 | HB585.1 | HB685.0 | HB685.1 | GB350 | GB370S | GB370.1S | GB370.2S | GB460C | GB460.1C

Tipo de máquina: Tractor cortacésped, Rider cortacésped, Biotrituradora, Motoazada,

Referencias OEM STIHL: 9503 003 6841, 9503 003 6841, 9503 003 6841

Referencias alternativas STIHL: 9503 003 6840, 9503 003 6840, 9503 003 6840

Denominaciones STIHL: Rodamiento, Coginete

Modelo de STIHL y VIKING: RT 4082.0, RT 4082.1, RT 4097.0 SX, RT 4097.1 SX, RT 5097.0, RT 5097.0 C, RT 5097.0 Z, RT 5097.1, RT 5097.1 Z, RT 5112.1 Z, RT 6112.0 C, RT 6112.0 ZL, RT 6112.1 ZL, RT 6127.0 ZL, RT 6127.1 ZL, GH 370.0 S, GH 370.1 S, GH 460.0 C, GH 460.1 C, MH 445.0, MH 445.1, MR 4082.0, MR 4082.0 K, MR 4082.1, MR 4082.2, MT 4097.0 SX, MT 4097.1 SX, MT 4112.0 S, MT 4112.1 S, MT 5097.0, MT 5097.0 C, MT 5097.0 G, MT 5097.0 K, MT 5097.0 Z, MT 5097.1, MT 5097.1 C, MT 5097.1 Z, MT 6112.0, MT 6112.0 C, MT 6112.0 K, MT 6112.0 ZL, MT 6112.1 C, MT 6112.1 ZL, MT 6127.0 KL, MT 6127.0 ZL, MT 6127.1 ZL, MT 640 (1996), MT 640 (1997), MT 680, AMS 127, HB 445.0, HB 445.0 R, HB 445.1, HB 445.1 R, HB 445.2, HB 445.2 R, HB 560.0, HB 585.0, HB 585.1, HB 685.0, HB 685.1, GB 350, GB 370 S, GB 370.1 S, GB 370.2 S, GB 460 C, GB 460.1 C

Tipo de recambio: Original OEM

Fabricante: STIHL

