

STIHL - 41441290900 - Junta brida de carburador lado del motor STIHL

BG56, BG66, BG86, BG86C, BR200, FS40 (Versiones4144), FS50 (Versiones4144), FS50C, FS56C, FS56RC, FS70C, FS70RC, HT56C, KM56RC, MM56, SH56, SH86, SH86C, SR200

Recambio original para las siguientes máquinas STIHL:

BG56 | BG56-D | BG66-D | BG86 | BG86C-E | BG86C-ED | BG86-D | BR200 | BR200-D | FS40 (4144) | FS50 (4144) | FS50C-E | FS56C-E | FS56RC-E | FS70C-E | FS70RC-E | HT56C-E | KM56RC-E | MM56 | SH56 | SH56-D | SH86 | SH86C-E | SH86C-ED | SH86-D | SR200 | SR200-D

Tipo de máquina: Soplador, Aspirador, Cortabordes, Desbrozadora, Podadora de altura, Motor sistema combinado, Multimotor

Referencias OEM STIHL: 41441290900, 4144 129 0900, 4144-129-0900

Denominaciones STIHL: Junta

Modelo de STIHL: BG 56, BG 56-D, BG 66-D, BG 86, BG 86 C-E, BG 86 C-E D, BG 86-D, BR 200, BR 200-D, FS 40 4144, FS 50 (4144), FS 50 C-E, FS 56 C-E, FS 56 RC-E, FS 70 C-E, FS 70 RC-E, HT 56 C-E, KM 56 RC-E, MM 56, SH 56, SH 56-D, SH 86, SH 86 C-E, SH 86 C-E D, SH 86-D, SR 200, SR 200-D

Tipo de recambio: Original OEM

Fabricante: STIHL

