

STIHL - 41141491205 - Junta de carburador lado filtro de aire STIHL

Para máquinas STIHL HT56C, FS38, FS40, FS45, FS50, FS55, FS56, FS70, FS120, FS200, FS250, FS235

También para modelos HS45, HS75, HS80, HS81, HS82, HS86, HS87, HL45, HL75, HL90, HL95, HL100, FH75, SP85, SP90, SR200D, SR430, SR450, KM55, KM56, KM85, KM90, KM100, KM111, KM130, KM131, KM235, MM56, BT120C, BT121, BG45, BG55, BG56, BG66, BG72, BG85, BG86, BR200, BR430, BR450, SH55, SH56, SH85, SH86, HT70, HT75, HT100, HT101, HT102, HT103, HT105, HT130, HT131, HT132, HT133, HT134, HT135, FS48, FS51, FS61, FS62, FS65, FS66, FS72, FS74, FS75, FS76, FS80, FS81, FS85, FS86, FS87, FS89, FS90, FS91, FS96, FS100, FS106, FS111, FS130, FS131, FS310, FS311, FR85T, FR106, FS131T, FR135, FR145, FR235, FC72, FC85, FC100, FC110, MM55, MM56, BT130, BT131, BG45, KW85, BR500, BR550, BR600, BR700, BR800C

Referencias STIHL: 41141491205, 4114 149 1205, 4114-149-1205

