

## **STIHL - 41287907501 - Tornillo de muletilla ajuste manillar desbrozadora STIHL**

Para máquinas STIHL FS90, FS91, FS111, FS120, FS130, FS131, FS200, FS240C, FS250, FS300, FS311, FS350, FS400, FS450, FSKM131, FSA80, FSA90, FSA120, FSA130, FSA135, KM85, KM90

Recambio original para las siguientes máquinas STIHL:

FSA90 | FS240-Z | FS120 | FS100 | FS200 | FS91 | FS80-4137 | BR450 | BR450C-EF | BT45-Z | KM90 | FS311 | BR600 | BR700 | BR500 | FS90-4180 | KM130 | FS400-K | FS240C-E | FS450 | FS131 | FS111 | FS310 | FS250 | FS130 | FS350 | FS450-K | BR550 | BR430 | RGA140 | FSA120.0 | FSA80.0 | BR800C-E | FSA130 | FSA135 | BGA300.1 | KM85

Tipo de máquina: Desbrozadora, Soplador, Motor sistema combinado

Referencias OEM STIHL: 41287907501, 4128 790 7501, 4128-790-7501

Referencias alternativas STIHL: 41287907500, 4128 790 7500, 4128-790-7500

Denominaciones STIHL: Tornillo de muletilla

Modelo de STIHL: FSA 90, FS 240-Z, FS 120, FS 100, FS 200, FS 91, FS 80 - 4137, BR 450, BR 450 C-EF, BT 45-Z, KM 90, FS 311, BR 600, BR 700, BR 500, FS 90 - 4180, KM 130, FS 400-K, FS 240 C-E, FS 450, FS 131, FS 111, FS 310, FS 250, FS 130, FS 350, FS 450-K, BR 550, BR 430, RGA 140, FSA 120.0, FSA 80.0, BR 800 C-E, FSA 130, FSA 135, BGA 300.1, KM 85

Tipo de recambio: Original OEM

Fabricante: STIHL

Medidas: Rosca: 6 mm

