

STIHL - 00024007000 - Bujía motor KOHLER cortacésped STIHL y VIKING

RM4.0RTP, RM650.0T, RM650.0V, RM655.0V, MB4.1RTP, MB650.3T, MB650.3V, MB655.3V, RM650.0T, RM650.0V, RM655.0V, MB650.3T, MB650.3V, MB655.3V

Recambio original para las siguientes máquinas STIHL y VIKING con motor KOHLER:

RM4.0RTP | RM650.0T | RM650.0V | RM655.0V | MB4.1RTP | MB650.3T | MB650.3V | MB655.3V |
RM650.0T | RM650.0V | RM655.0V | MB650.3T | MB650.3V | MB655.3V | XT-6 | XT-675 | HD775 (HD775-3027) | XT-800 (XT800-3090)

Tipo de máquina: Cortacésped

Referencias OEM STIHL: 00024007000, 0002 400 7000, 0002-400-7000

Referencias KOHLER: 1413211S

Denominaciones STIHL: Bujía

Modelo de STIHL y VIKING: RM 4.0 RTP, RM 650.0 T, RM 650.0 V, RM 655.0 V, HD775 (HD775-3027), MB 4.1 RTP, MB 650.3 T, MB 650.3 V, MB 655.3 V, RM 650.0 T, RM 650.0 V, RM 655.0 V, XT-800 (XT800-3090), MB 650.3 T, MB 650.3 V, MB 655.3 V, XT-6

Tipo de recambio: Original OEM

Fabricante: STIHL

KOHLER

