

BRIGGS & STRATTON - 691449 - Arbol de levas motor Briggs & Stratton

Para motores BRIGGS & STRATTON modelos: 120502, 120H02, 120H07, 120K02, 120L02, 120T02, 121H02, 121H82, 121K02, 121K12, 122H02, 122H07, 122H82, 122K02, 122K05, 122K07, 122K09, 122K12, 122K82, 122L02, 122L05, 122L07, 122M02, 122M05, 122M07, 122T02, 122T05, 122T07, 123702, 123707, 123782, 123787, 123802, 123807, 123882, 123887, 123H02, 123H07, 123J02, 123J09, 123K02, 123K05, 123K07, 123K09, 123K12, 124702, 124707, 124782, 124787, 124802, 124807, 124882, 124887, 124H02, 124H82, 124K02, 124L02, 124L05, 124L07, 124T02, 124T05, 124T07, 124T12, 125702, 125782, 125H02, 125H07, 125H82, 125K02, 125K05, 125K07, 125K09, 126702, 126707, 126782, 126787, 126802, 126807, 126882, 126K02, 126L02, 126L05, 126L07, 126L12, 126M02, 126M05, 126M07, 126T02, 126T05, 126T07, 126T12, 127702, 127707, 127712, 127782, 127802, 127807, 127809, 127882, 127887, 127H02, 127H07, 128702, 128712, 128802, 128805, 128807, 128809, 128812, 128882, 128887, 128H02, 128H07, 128L02, 128L05, 128L07, 128T02, 128T05, 128T07, 129702, 129707, 129782, 129787, 129802, 129807, 129812, 129882, 129887, 129H02, 129H07, 12A802, 12B802, 12C702, 12C802, 12C807, 12C882, 12D802, 12E802, 12E807, 12F702, 12F707, 12F782, 12F802, 12F805, 12F807, 12F809, 12F812, 12F882, 12F887, 12F889, 12G702, 12G782, 12G802, 12G807, 12G812, 12G882, 12H702, 12H707, 12H712, 12H802, 12H805, 12H807, 12H809, 12H812, 12H882, 12J702, 12J707, 12J802, 12J805, 12J807, 12J809, 12J887, 12J902, 12J907, 12K702, 12L802, 12L882, 12L887, 12L902, 12M802, 12M807, 12M882, 12M887, 12M902, 12P802, 12Q802, 12T702, 12T707, 12T802, 12T807, 12T882, 12T887, 12U802, 12V802, 12V807, 12V809, 12V882, 12W802, 12W807, 12X802, 12X812, 12X882, 12Y802, 12Z802

Sustituye a referencias BRIGGS: 498275, 691449, 498817, 492830

¡Nota! Si no está seguro de que la pieza sea la correcta, contacte con nosotros con los números de su motor (modelo, tipo y código) y nosotros lo comprobamos.



