

STIHL - 11290071000 - Juego engranaje y tornillo tensor de cadena motosierra STIHL

MS201TC, MS201T, MS201C, MS200T, MS194TC, MS194T, MS194C, MS193TC, MS193T, MS193C, MS192T, MS192C, MS151TC, MS151C, MS150TC, MC200, HT-KM, HTE60, HT75, HT70, HT132, HT131, HT130, HT101, HT100, HT

Recambio original para las siguientes máquinas STIHL:

MS201TC-M | MS201T | MS201C-M | MS200T | MS194TC-E | MS194T | MS194C | MS193TC-E | MS193T | MS193C-E | MS192T | MS192C-E | MS151TC-E | MS151C-E | MS150TC | MC200 | HT-KM | HTE60 | HT75 | HT70 | HT132 | HT131 | HT130 | HT101 | HT100 | HT

Tipo de máquina: Motosierra, Podadora de altura

Referencias OEM STIHL: 11290071000, 1129 007 1000, 1129-007-1000

Denominaciones STIHL: Juego engranaje recto / tornillo tensor

Modelo de STIHL: MS 201 TC-M, MS 201 T, MS 201 C-M, MS 200 T, MS 194 TC-E, MS 194 T, MS 194 C, MS 193 TC-E, MS 193 T, MS 193 C-E, MS 192 T, MS 192 C-E, MS 151 TC-E, MS 151 C-E, MS 150 TC, MC 200, HT-KM, HTE 60, HT 75, HT 70, HT 132, HT 131, HT 130, HT 101, HT 100, HT

Tipo de recambio: Original OEM

Fabricante: STIHL



