

**STIHL - 11296405000 - Horquilla de suplemento freno cadena motosierra STIHL**

020T, MS150, MS150TC, MS151C, MS151TC, MS192C, MS192T, MS192TC, MS193C, MS193T, MS193TC, MS194C, MS194T, MS194TC, MS200, MS200T, MS201, MS201C, MS201T, MS201TC

Recambio original para las siguientes máquinas STIHL:

020T | MC200 | MS150C-E | MS150TC-E | MS151C-E | MS151TC-E | MS192C-E | MS192T | MS192TC-E | MS193C-E | MS193T | MS193TC-E | MS194C-E | MS194T | MS194TC-E | MS200 | MS200T | MS201 | MS201C-M | MS201T | MS201TC-M

Tipo de máquina: Motosierra

Referencias OEM STIHL: 11296405000, 1129 640 5000, 1129-640-5000

Denominaciones STIHL: Suplemento, Horquilla, Pletina, Guarnición

Modelo de STIHL: 020 T, MC 200, MS 150 C-E, MS 150 TC-E, MS 151 C-E, MS 151 TC-E, MS 192 C-E, MS 192 T, MS 192 TC-E, MS 193 C-E, MS 193 T, MS 193 TC-E, MS 194 C-E, MS 194 T, MS 194 TC-E, MS 200, MS 200 T, MS 201, MS 201 C-M, MS 201 T, MS 201 TC-M

Tipo de recambio: Original OEM

Fabricante: STIHL





