

STIHL - 00004051005 - Capuchón de bujía STIHL

MS150C, MS151C, HT105, HT130, HT131, HT134, HT135, FS89, FS91, FS131, FS240C-E, FS260C, FS261C, FS311, FS360C, FS410C, FS361C, FS411C, FS460C, FS461C, SP452, SP482, KM111R, KM131R, BT131, BR800C

Recambio original para las siguientes máquinas STIHL:

MS150C-E | MS150TC-E | MS151TC-E | MS151C-E | HT102 | HT103 | HT105 | HT130 | HT131 | HT132 | HT133 | HT134 | HT135 | FS89 | FS89R | FS91 | FS91R | FS111 | FS131 | FS131R | FS240C-E | FS240RC-E | FS260 | FS260C-E | FS261C-E | FS311 | FS360C-E (Versión 4147) | FS410C-E | FS360C-EM (Versión 4147) | FS410C-EM | FS361C-EM | FS361.0C-EM | FS411C-EM | FS411.0C-EM | FS460C-EM | FS461C-EM | FS461.0C-EM | FR131T | FR410C-E | FR460TC-EFM | FR460TC-EM | SP452 | SP482 | KM111R | KM131 | KM131R | BT131 | BR800C-E

Tipo de máquina: Desbrozadora, Motosierra, Podadora de altura, Vareador, Soplador, Motor sistema combinado, Ahoyador

Referencias OEM STIHL: 00004051005, 0000 405 1005, 0000-405-1005

Denominaciones STIHL: Capuchón, Pipeta, Enchufe

Modelo de STIHL: MS 150 C-E, MS 150 TC-E, MS 151 TC-E, MS 151 C-E, HT 102, HT 103, HT 105, HT 130, HT 131, HT 132, HT 133, HT 134, HT 135, FS 89, FS 89 R, FS 91, FS 91 R, FS 111, FS 131, FS 131 R, FS 240 C-E, FS 240 RC-E, FS 260, FS 260 C-E, FS 261 C-E, FS 311, FS 360 C-E (Versión 4147), FS 410 C-E, FS 360 C-EM (Versión 4147), FS 410 C-EM, FS 361 C-EM, FS 361.0 C-EM, FS 411 C-EM, FS 411.0 C-EM, FS 460 C-EM, FS 461 C-EM, FS 461.0 C-EM, FR 131 T, FR 410 C-E, FR 460 TC-EFM, FR 460 TC-EM, SP 452, SP 482, KM 111 R, KM 131, KM 131 R, BT 131, BR 800 C-E

Tipo de recambio: Original OEM

Fabricante: STIHL

