

STIHL - 11226495000 - Anillo de junta de goma bomba aceite motosierra STIHL

046, 066, 088, MS241, MS261, MS271, MS291, MS341, MS361, MS362, MS400, MS441, MS460, MS461, MS462, MS500i, MS650, MS660, MS661, MS880, MS881, MSA300

Recambio original para las siguientes máquinas STIHL:

046 | 066 | 088 | 046C | 046 Magnum BR | 046W | 066BR | 066M | 066MR | 066W | MS241C-M | MS261 | MS261C-BE | MS261C-BM | MS261C-M | MS261C-MQ | MS261C-Q | MS271 | MS271C-BE | MS291 | MS291C-BE | MS291C-BEQ | MS341 | MS361 | MS362 | MS362C-M | MS400C-M | MS400.1C-M | MS400.1C-MR | MS400.1C-MVW Arctic | MS441 | MS441C-M | MS460 | MS460 Magnum | MS460-R | MS461 | MS461-R | MS462C-M | MS462C-MR Rettungssäge | MS500i | MS650 | MS660 | MS660-W | MS661C-M | MS880 | MS881 | MSA300.0C-O | MSA300.1 | MSA300.1C-O

Tipo de máquina: Motosierra

Referencias OEM STIHL: 11226495000, 1122 649 5000, 1122-649-5000

Denominaciones STIHL: Anillo de junta B4x2, Goma, Retén

Modelo de STIHL: 046, 066, 088, 046 C, 046 Magnum BR, 046 W, 066 BR, 066 M, 066 MR, 066 W, MS 241 C-M, MS 261, MS 261 C-BE, MS 261 C-BM, MS 261 C-M, MS 261 C-MQ, MS 261 C-Q, MS 271, MS 271 C-BE, MS 291, MS 291 C-BE, MS 291 C-BEQ, MS 341, MS 361, MS 362, MS 362 C-M, MS 400 C-M, MS 400.1 C-M, MS 400.1 C-M R, MS 400.1 C-M VW Arctic, MS 441, MS 441 C-M, MS 460, MS 460 Magnum, MS 460-R, MS 461, MS 461-R, MS 462 C-M, MS 462 C-M R Rettungssäge, MS 500i, MS 650, MS 660, MS 660-W, MS 661 C-M, MS 880, MS 881, MSA 300.0 C-O, MSA 300.1, MSA 300.1 C-O

Tipo de recambio: Original OEM

Fabricante: STIHL



