

## **STIHL - 63757067305 - Protector lateral derecho chasis cortacésped VIKIKG**

MB650.0KS, MB650.0T, MB650.0TK, MB650.0V, MB650.0VS, MB650.1V, MB655.0G, MB655.0GK, MB655.0KS, MB655.0V, MB655.1G, MB655.1V, MB655.1VS, MB750.0GK, MB750.1GK, MB750.1KS, MB750.2KS, MB755.0KS, MB755.1KS

Recambio original para las siguientes máquinas VIKING:

MB650.0KS | MB650.0T | MB650.0TK | MB650.0V | MB650.0VE | MB650.0VQ | MB650.0VS | MB650.1V | MB655.0G | MB655.0GK | MB655.0GQ | MB655.0KS | MB655.0V | MB655.1G | MB655.1V | MB655.1VR | MB655.1VS | MB750.0GK | MB750.1GK | MB750.1KS | MB750.2KS | MB755.0KS | MB755.1KS | MB755.2KS

Tipo de máquina: Cortacésped

Referencias OEM STIHL: 63757067305, 6375 706 7305, 6375-706-7305

Denominaciones STIHL: Regleta de protección, Protector lateral chasis

Modelo de VIKING: MB 650.0 KS, MB 650.0 T, MB 650.0 TK, MB 650.0 V, MB 650.0 VE, MB 650.0 VQ, MB 650.0 VS, MB 650.1 V, MB 655.0 G, MB 655.0 GK, MB 655.0 GQ, MB 655.0 KS, MB 655.0 V, MB 655.1 G, MB 655.1 V, MB 655.1 VR, MB 655.1 VS, MB 750.0 GK, MB 750.1 GK, MB 750.1 KS, MB 750.2 KS, MB 755.0 KS, MB 755.1 KS, MB 755.2 KS

Tipo de recambio: Original OEM

Fabricante: STIHL



