

STIHL - 91040074260 - Tornillo autoroscante P5x12mm

Recambio original para las siguientes máquinas STIHL:

RM248.0 | RM248.0T | RM248.1 | RM248.1T | RM253.0T | RM253.1T | RMA2.2RV | RMA443.2VC | RMA448.2VC | RMI422.0 | RMI422.0P | RMI422.0PC | RMI422.1 | RMI422.1P | RMI422.1PC | RMI422.2 | RMI422.2P | RMI422.2PC | RMI522.0C | RMI632.0 | RMI632.0C | RMI632.0P | RMI632.0PC | RMI632.1 | RMI632.1C | RMI632.1P | RMI632.1PC | RT4082.0 | RT4082.1 | RT5097.0 | RT5097.0C | RT5097.0Z | RT5097.1 | RT5097.1Z | RT5112.1Z | RT6112.0C | RT6112.0ZL | RT6112.1ZL | RT6127.0ZL | RT6127.1ZL | RL540.0 | GH370.0S | GHE105.0 | GHE150.0 | GHE250.0 | GHE250.0S | GHE355.0 | MB248.3 | MB248.3T | MB248.4 | MB253.0T | MB253.1T | MB400 | MB400X | MB400M | MB410 | MB460 | MB415 | MB465 | MB443.0 | MB443.0C | MB443.0T | MB443.1T | MB448.0 | MB448.0T | MB448.0TX | MB448.1T | MB448.1TC | MB448.1TX | MB450 | MB450X | MB450M | MB455BC | MB455 | MB455E | MB455M | MB455MM | MB455C | MB500 | MB505BS | MB505MQ | MB505S | MB505C | MB505 | MB505E | MB505KAT | MB505M | MB505MM | MB555BS | MB555KS | MB555MQ | MB555PRO | MB555S | MB555C | MB555 | MB555E | MB555M | MB858.0 | MA400 | MA450 | ME400 | ME400M | ME410 | ME443.0 | ME443.0C | ME450 | ME450M | ME455 | MI422.0 | MI422.0P | MI422.1 | MI422.1P | MI422.1PC | MI632.0 | MI632.0C | MI632.0P | MI632.0PC | MI632.1 | MI632.1C | MI632.1P | MI632.1PC | ADO400 | LB540 | LB540.1 | LE540 | MR4082.0 | MR4082.0K | MR4082.1 | MR4082.2 | MT5097.0 | MT5097.0C | MT5097.0G | MT5097.0K | MT5097.0Z | MT5097.1 | MT5097.1C | MT5097.1Z | MT6112.0 | MT6112.0C | MT6112.0K | MT6112.0ZL | MT6112.1C | MT6112.1ZL | MT6127.0KL | MT6127.0ZL | MT6127.1ZL | GB460.1C | GE103 | GE105 | GE101 | GE103.1 | GE105.1 | GE150.1 | GE250.1 | GE250.1S | GE355.1 | GE420.1 | GE450.1

Tipo de máquina: Cortacésped, Robot Cortacésped, Tractor Cortacésped, Biotrituradora

Referencias OEM STIHL: 91040074260, 9104 007 4260, 9104-007-4260

Denominaciones STIHL: Tornillo

Modelo de STIHL: RM 248.0, RM 248.0 T, RM 248.1, RM 248.1 T, RM 253.0 T, RM 253.1 T, RMA 2.2 RV, RMA 443.2 VC, RMA 448.2 VC, RMI 422.0, RMI 422.0 P, RMI 422.0 PC, RMI 422.1, RMI 422.1 P, RMI 422.1 PC, RMI 422.2, RMI 422.2 P, RMI 422.2 PC, RMI 522.0 C, RMI 632.0, RMI 632.0 C, RMI 632.0 P, RMI 632.0 PC, RMI 632.1, RMI 632.1 C, RMI 632.1 P, RMI 632.1 PC, RT 4082.0, RT 4082.1, RT 5097.0, RT 5097.0 C, RT 5097.0 Z, RT 5097.1, RT 5097.1 Z, RT 5112.1 Z, RT 6112.0 C, RT 6112.0 ZL, RT 6112.1 ZL, RT 6127.0 ZL, RT 6127.1 ZL, RL 540.0, GH 370.0 S, GHE 105.0, GHE 150.0, GHE 250.0, GHE 250.0 S, GHE 355.0, MB 248.3, MB 248.3 T, MB 248.4, MB 253.0 T, MB 253.1 T, MB 400, MB 400 X, MB 400 M, MB 410, MB 460, MB 415, MB 465, MB 443.0, MB 443.0 C, MB 443.0 T, MB 443.1 T, MB 448.0, MB 448.0 T, MB 448.0 TX, MB 448.1 T, MB 448.1 TC, MB 448.1 TX, MB 450, MB 450 X, MB 450 M, MB 455 BC, MB 455, MB 455 E, MB 455 M, MB 455 MM, MB 455 C, MB 500, MB 505 BS, MB 505 MQ, MB 505 S, MB 505 C, MB 505, MB 505 E, MB 505 KAT, MB 505 M, MB 505 MM, MB 555 BS, MB 555 KS, MB 555 MQ, MB 555 PRO, MB 555 S, MB 555 C, MB 555, MB 555 E, MB 555 M, MB 858.0, MA 400, MA 450, ME 400, ME 400 M, ME 410, ME 443.0, ME 443.0 C, ME 450, ME 450 M, ME 455, MI 422.0, MI 422.0 P, MI 422.1, MI 422.1 P, MI 422.1 PC, MI 632.0, MI 632.0 C, MI 632.0 P, MI 632.0 PC, MI 632.1, MI 632.1 C, MI 632.1 P, MI 632.1 PC, ADO 400, LB 540, LB 540.1, LE 540, MR 4082.0, MR 4082.0 K, MR 4082.1, MR 4082.2, MT

5097.0, MT 5097.0 C, MT 5097.0 G, MT 5097.0 K, MT 5097.0 Z, MT 5097.1, MT 5097.1 C, MT 5097.1 Z, MT 6112.0, MT 6112.0 C, MT 6112.0 K, MT 6112.0 ZL, MT 6112.1 C, MT 6112.1 ZL, MT 6127.0 KL, MT 6127.0 ZL, MT 6127.1 ZL, GB 460.1 C, GE 103, GE 105, GE 101, GE 103.1, GE 105.1, GE 150.1, GE 250.1, GE 250.1 S, GE 355.1, GE 420.1, GE 450.1

Tipo de recambio: Original OEM

Fabricante: STIHL

Medidas: P5 x 12 mm

