

STIHL - 90223191028 - Tornillo IS-M5x14mm

FSA135, FSA135R, FSA200.0, FSA200.0R, FSA400.0, HLA135, HTA135, HTA150.0, HTA160.0, KMA135R, KMA200.0R, MS182, MS182C, MS231, MS231C, MS251, MS251C, MS271, MS271C, MS291, MSA300, RGA140, TSA300.0

Recambio original para las siguientes máquinas STIHL:

FSA135 | FSA135R | FSA200.0 | FSA200.0R | FSA400.0 | HLA135 | HLA135K | HTA135 | HTA150.0 | HTA160.0 | KMA135R | KMA200.0R | MS182 | MS182C-BE | MS231 | MS231C-BE | MS251 | MS251C-BE | MS271 | MS271C-BE | MS291 | MS291C-BE | MS291C-BEQ | MSA300 | MSA300.0C-O | MSA300.1 | MSA300.1C-O | RGA140 | TSA300.0

Tipo de máquina: Motosierra, Desbrozadora, Motor sistema combinado, Tronzadora

Referencias OEM STIHL: 90223191028, 9022 319 1028, 9022-319-1028

Denominaciones STIHL: Tornillo IS-M5x14

Modelo de STIHL: FSA 135, FSA 135 R, FSA 200.0, FSA 200.0 R, FSA 400.0, HLA 135, HLA 135 K, HTA 135, HTA 150.0, HTA 160.0, KMA 135 R, KMA 200.0 R, MS 182, MS 182 C-BE, MS 231, MS 231 C-BE, MS 251, MS 251 C-BE, MS 271, MS 271 C-BE, MS 291, MS 291 C-BE, MS 291 C-BEQ, MSA 300, MSA 300.0 C-O, MSA 300.1, MSA 300.1 C-O, RGA 140, TSA 300.0

Tipo de recambio: Original OEM

Fabricante: STIHL

Medidas: IS-M 5 x 14 mm



