

STIHL - 42266416500 - Tornillo de engrase caja reductora cortasetos STIHL

HL, HL 0°, HL 0° 90°, HL100, HL 145°, HL30°, HL75, HL94C, HLA135, HLA140.0, HLA150.0, HL-KM, HL-KM 0° 90°, HL-KM 145°, HL-KM 30°, HS75, HS80, HS81R, HS82R, HS85, HS86R, HS87R, HSA100.0, HSA130.0R

Recambio original para las siguientes máquinas STIHL:

HL | HL0° | HL0°90° | HL100 | HL100K | HL145° | HL30° | HL45 | HL75 | HL75K | HL92C-E | HL94C-E | HL94KC-E | HLA135 | HLA140.0 | HLA150.0 | HL-KM | HL-KM0° | HL-KM0°90° | HL-KM145° | HL-KM30° | HS246 | HS72 | HS74 | HS75 | HS76 | HS80 | HS81R | HS81T | HS82R | HS82T | HS85 | HS86R | HS86T | HS87R | HSA100.0 | HSA100.1 | HSA130.0R | HSA130.0T | HSA60.0 | HSA60.1 | HSA94R | HSA94T | FH0°90° | FH75 | FH-KM0°90° | FH-KM145° | HEL600 | HEL600K | HEL700 | HEL700K | HG100 | HG300 | HG900

Tipo de máquina: Cortasetos

Referencias OEM STIHL: 42266416500, 4226 641 6500, 4226-641-6500

Referencias alternativas STIHL: 41177136501, 4117 713 6501, 4117-713-6501, 41177136500, 4117 713 6500, 4117-713-6500

Denominaciones STIHL: Tornillo de cierre, Tapón de engrase

Modelo de STIHL: HL, HL 0°, HL 0° 90°, HL 100, HL 100 K, HL 145°, HL 30°, HL 45, HL 75, HL 75 K, HL 92 C-E, HL 94 C-E, HL 94 KC-E, HLA 135, HLA 140.0, HLA 150.0, HL-KM, HL-KM 0°, HL-KM 0° 90°, HL-KM 145°, HL-KM 30°, HS 246, HS 72, HS 74, HS 75, HS 76, HS 80, HS 81 R, HS 81 T, HS 82 R, HS 82 T, HS 85, HS 86 R, HS 86 T, HS 87 R, HSA 100.0, HSA 100.1, HSA 130.0 R, HSA 130.0 T, HSA 60.0, HSA 60.1, HSA 94 R, HSA 94 T, FH 0° 90°, FH 75, FH-KM 0° 90°, FH-KM 145°, HEL 600, HEL 600 K, HEL 700, HEL 700 K, HG 100, HG 300, HG 900

Tipo de recambio: Original OEM

Fabricante: STIHL

