

STIHL - 00009511100 - Tornillo IS-D5x20mm

BG56, BG85, BG86, FS38, FS400, FS450, FS480, HL75, HS452-MIX, HS87R, HSA130.0T, HSA94R, HT, HT100, HT101, HT70, HT75, HTA135, HTA160.0, MA443.1, MS162, MSA220.0C, MSA70.0C, SP471, SR200, TS410, TS440

Recambio original para las siguientes máquinas STIHL:

BG56-D | BG85 | BG86-D | FR450 | FR480C-F (4128) | FS38 | FS382-MIX | FS400-K | FS450 | FS480 | HL75 | HL75K | HS45 2-MIX | HS87R | HSA130.0T | HSA94R | HSA94T | HT | HT100 | HT101 | HT70 | HT75 | HTA135 | HTA160.0 | MA443.1 | MS162 | MS162C-BE | MSA220.0C-B | MSA70.0C-B | SP471 | SP481 | SR200 | TS410 | TS440-A | TS710.0i

Tipo de máquina: Soplador, Desbrozadora, Cortabordes, Cortasetos, Motosierra, Podadora de altura, Atomizador, Vareador

Referencias OEM STIHL: 00009511100, 0000 951 1100, 0000-951-1100

Referencias alternativas STIHL: 00009511192, 0000 951 1192, 0000-951-1192

Denominaciones STIHL: Tornillo

Modelo de STIHL: BG 56-D, BG 85, BG 86-D, FR 450, FR 480 C-F (4128), FS 38, FS 38 2-MIX, FS 400-K, FS 450, FS 480, HL 75, HL 75 K, HS 45 2-MIX, HS 87 R, HSA 130.0 T, HSA 94 R, HSA 94 T, HT, HT 100, HT 101, HT 70, HT 75, HTA 135, HTA 160.0, MA 443.1, MS 162, MS 162 C-BE, MSA 220.0 C-B, MSA 70.0 C-B, SP 471, SP 481, R 200, TS 410, TS 440-A, TS 710.0i

Tipo de recambio: Original OEM

Fabricante: STIHL

Medidas: IS-D 5 x 20 mm

