

STIHL - 61057047400 - Piñón tracción rueda izquierda cortacésped STIHL y VIKING

MB248.1T, MB248.2T, MB248.3T, MB253.0T, MB443.0T, MB448.0T, MB455, MB505, MB545.0T, MB555, MB650.0T, MB655.0V, MB755.0KS, MB756.0YC, RM248.0T, RM248.1T, RM248.2T, RM253.0T, RM443.0T, RM448.0T, RM545.0

Recambio original para las siguientes máquinas STIHL:

RM248.0T | RM248.1T | RM248.2T | RM253.0T | RM253.1T | RM253.2T | RM3.0RT | RM3.1RT | RM4.0RTP | RM4.1RT | RM443.0T | RM443.1T | RM448.0PC | RM448.0T | RM448.0TC | RM448.0VC | RM448.1PC | RM448.1VC | RM545.0T | RM545.0V | RM545.0VE | RM545.1T | RM545.1V | RM545.1VE | RM650.0T | RM650.0V | RM650.0VS | RM655.0V | RM655.0VS | RM655.0YS | RM655.1VS | RM655.1YS | RM756.0YC | RM756.0YS | RMA2.1RT | RMA2.2RV | RMA443.0TC | RMA443.1TC | RMA443.2VC | RMA448.0TC | RMA448.1TC | RMA448.2VC | RMA7.0RV | RMA7.0RVSET | RMA750.0V | RMA756.0V | RMA765.0V | RME545.0V

Recambio original para las siguientes máquinas VIKING:

MB248.1T | MB248.2T | MB248.3T | MB253.0T | MB253.1T | MB3RT | MB3.1RT | MB3.2RT | MB4.0RTP | MB4.1RTP | MB415 | MB443.0T | MB443.1T | MB448.0T | MB448.0TX | MB448.1T | MB448.1TC | MB448.1TX | MB448.1VC | MB455 | MB455BC | MB455C | MB455E | MB455M | MB455MM | MB465 | MB505 | MB505BS | MB505C | MB505E | MB505KAT | MB505M | MB505MM | MB505MQ | MB505S | MB545.0T | MB545.0V | MB545.0VE | MB545.0VR | MB545.0VS | MB545.1T | MB545.1V | MB545.1VE | MB545.1VR | MB555 | MB555BS | MB555C | MB555E | MB555KS | MB555M | MB555MQ | MB555PRO | MB555S | MB650.0KS | MB650.0T | MB650.0TK | MB650.0V | MB650.0VE | MB650.0VQ | MB650.0VS | MB650.1V | MB650.3T | MB650.3V | MB650.3VS | MB655.0G | MB655.0GK | MB655.0GQ | MB655.0KS | MB655.0V | MB655.1G | MB655.1V | MB655.1VR | MB655.1VS | MB655.3V | MB655.3VS | MB655.3YS | MB750.0GK | MB750.1GK | MB750.1KS | MB750.2KS | MB755.0KS | MB755.1KS | MB755.2KS | MB756.0YC | MB756.0YS | ME455 | ME545.0V

Tipo de máquina: Cortacésped

Referencias OEM STIHL: 61057047400, 6105 704 7400, 6105-704-7400

Referencias alternativas STIHL: 00006402500, 0000 640 2500, 0000-640-2500

Denominaciones STIHL: Piñón metálico

Modelo de STIHL: RM 248.0 T, RM 248.1 T, RM 248.2 T, RM 253.0 T, RM 253.1 T, RM 253.2 T, RM 3.0 RT, RM 3.1 RT, RM 4.0 RTP, RM 4.1 RT, RM 443.0 T, RM 443.1 T, RM 448.0 PC, RM 448.0 T, RM 448.0 TC, RM 448.0 VC, RM 448.1 PC, RM 448.1 VC, RM 545.0 T, RM 545.0 V, RM 545.0 VE, RM 545.1 T, RM 545.1 V, RM 545.1 VE, RM 650.0 T, RM 650.0 V, RM 650.0 VS, RM 655.0 V, RM 655.0 VS, RM 655.0 YS, RM 655.1 VS, RM 655.1 YS, RM 756.0 YC, RM 756.0 YS, RMA 2.1 RT, RMA 2.2 RV, RMA 443.0 TC,

RMA 443.1 TC, RMA 443.2 VC, RMA 448.0 TC, RMA 448.1 TC, RMA 448.2 VC, RMA 7.0 RV, RMA 7.0 RV SET, RMA 750.0 V, RMA 756.0 V, RMA 765.0 V, RME 545.0 V

Modelo de VIKING: MB 248.1 T, MB 248.2 T, MB 248.3 T, MB 253.0 T, MB 253.1 T, MB 3 RT, MB 3.1 RT, MB 3.2 RT, MB 4.0 RTP, MB 4.1 RTP, MB 415, MB 443.0 T, MB 443.1 T, MB 448.0 T, MB 448.0 TX, MB 448.1 T, MB 448.1 TC, MB 448.1 TX, MB 448.1 VC, MB 455, MB 455 BC, MB 455 C, MB 455 E, MB 455 M, MB 455 MM, MB 465, MB 505, MB 505 BS, MB 505 C, MB 505 E, MB 505 KAT, MB 505 M, MB 505 MM, MB 505 MQ, MB 505 S, MB 545.0 T, MB 545.0 V, MB 545.0 VE, MB 545.0 VR, MB 545.0 VS, MB 545.1 T, MB 545.1 V, MB 545.1 VE, MB 545.1 VR, MB 555, MB 555 BS, MB 555 C, MB 555 E, MB 555 KS, MB 555 M, MB 555 MQ, MB 555 PRO, MB 555 S, MB 650.0 KS, MB 650.0 T, MB 650.0 TK, MB 650.0 V, MB 650.0 VE, MB 650.0 VQ, MB 650.0 VS, MB 650.1 V, MB 650.3 T, MB 650.3 V, MB 650.3 VS, MB 655.0 G, MB 655.0 GK, MB 655.0 GQ, MB 655.0 KS, MB 655.0 V, MB 655.1 G, MB 655.1 V, MB 655.1 VR, MB 655.1 VS, MB 655.3 V, MB 655.3 VS, MB 655.3 YS, MB 750.0 GK, MB 750.1 GK, MB 750.1 KS, MB 750.2 KS, MB 755.0 KS, MB 755.1 KS, MB 755.2 KS, MB 756.0 YC, MB 756.0 YS, ME 455, ME 545.0 V

Tipo de recambio: Original OEM

Fabricante: STIHL



