

STIHL - 90754784085 - Tornillo cilíndrico IS-D5x18mm

Recambio original para las siguientes máquinas STIHL:

FC85 | FH75 | FR85T | FS75 | FS80-4137 | FS80R-4137 | FS85 | FS85R | FS85T | FS94C-E | FS94RC-E | FSA130 | FSA130R | HL75 | HL75K | HL92C-E | HL94C-E | HL94KC-E | HS45 | HS452-MIX | HS46 | HS46C-E | HS56C-E | HT70 | HT75 | HTA65 | HTA85 | KM85 | KM85R | KM94RC-E | KMA130R | KW85 | MS171 | MS181 | MS181C-BE | MS211 | MS211C-BE | MS231 | MS231C-BE | MS251 | MS251C-BE | MS270 | MS270C-B | MS271 | MS271C-BE | MS280 | MS291 | MS291C-BE | MS291C-BEQ | MSA160T | MSA161T | SHA140.0 | SHA56 | SP200 | SP400 | SP450 | SP81 | SP85 | SPA65

Tipo de máquina: Desbrozadora, Motosierra, Cortasetos, Motor sistema combinado, Vareador

Referencias OEM STIHL: 90754784085, 9075 478 4085, 9075-478-4085

Denominaciones STIHL: Tornillo cilíndrico IS-D5x18

Modelo de STIHL: FC 85, FH 75, FR 85 T, FS 75, FS 80 - 4137, FS 80 R - 4137, FS 85, FS 85 R, FS 85 T, FS 94 C-E, FS 94 RC-E, FSA 130, FSA 130 R, HL 75, HL 75 K, HL 92 C-E, HL 94 C-E, HL 94 KC-E, HS 45, HS 45 2-MIX, HS 46, HS 46 C-E, HS 56 C-E, HT 70, HT 75, HTA 65, HTA 85, KM 85, KM 85 R, KM 94 RC-E, KMA 130 R, KW 85, MS 171, MS 181, MS 181 C-BE, MS 211, MS 211 C-BE, MS 231, MS 231 C-BE, MS 251, MS 251 C-BE, MS 270, MS 270 C-B, MS 271, MS 271 C-BE, MS 280, MS 291, MS 291 C-BE, MS 291 C-BEQ, MSA 160 T, MSA 161 T, SHA 140.0, SHA 56, SP 200, SP 400, SP 450, SP 81, SP 85, SPA 65

Tipo de recambio: Original OEM

Fabricante: STIHL

Medidas: IS - D5 x 18 mm

