

STIHL - 11236603001 - Disco dentado tensor cadena motosierra STIHL

MS162C, MS170C, MS172C, MS180C, MS181C, MS182C, MS210C, MS211C, MS212C, MS230C, MS231C, MS250C, MS251C, MSA120C, MSA140C, MSA160C, MSA200C, MSA220C, MSA60.0C, MSA70.0C, MSA80.0C, MSE140C, MSE160C

Recambio original para las siguientes máquinas STIHL:

017C | 018C | 019T | 023L | E180C | MS162C-BE | MS170C-ED | MS170-D | MS172C-BE | MS180C-B | MS180C-BD | MS180C-BE | MS181C-BE | MS182C-BE | MS210C-BE | MS211C-BE | MS212C-BE | MS230C-B | MS230C-BE | MS231C-BE | MS250C-BE | MS251C-BE | MSA120C-B | MSA140C-B | MSA160C-B | MSA160.0C-B | MSA200C-B | MSA200.0C-B | MSA220C-B | MSA220.0C-B | MSA60.0C-B | MSA70.0C-B | MSA80.0C-B | MSE140C-BQ | MSE160C-BQ | MSE170C-BQ | MSE180C-BQ | MSE190C-BQ | MSE200C-BQ | MSE210C-BQ | MSE230C-BQ
MSE210C-BQ | MSE230C-BQ

Tipo de máquina: Motosierra

Referencias OEM STIHL: 11236603001, 1123 660 3001, 1123-660-3001

Referencias alternativas STIHL: 11236603000, 1123 660 3000, 1123-660-3000

Denominaciones STIHL: Disco tensor cadena, Corona, Piñón

Modelo de STIHL: 017 C, 018 C, 019 T, 023 L, E 180 C, MS 162 C-BE, MS 170 C-E D, MS 170-D, MS 172 C-BE, MS 180 C-B, MS 180 C-B D, MS 180 C-BE, MS 181 C-BE, MS 182 C-BE, MS 210 C-BE, MS 211 C-BE, MS 212 C-BE, MS 230 C-B, MS 230 C-BE, MS 231 C-BE, MS 250 C-BE, MS 251 C-BE, MSA 120 C-B, MSA 140 C-B, MSA 160 C-B, MSA 160.0 C-B, MSA 200 C-B, MSA 200.0 C-B, MSA 220 C-B, MSA 220.0 C-B, MSA 60.0 C-B, MSA 70.0 C-B, MSA 80.0 C-B, MSE 140 C-BQ, MSE 160 C-BQ, MSE 170 C-BQ, MSE 180 C-BQ, MSE 190 C-BQ, MSE 200 C-BQ, MSE 210 C-BQ, MSE 230 C-BQ

Tipo de recambio: Original OEM

El Disco dentado incluye:

1 - 90413190600 Tornillo cillíndrico M4x5mm

