

STIHL - 41407907501 - Tornillo de muletilla ajuste vástago de transmisión STIHL

FS55T, SP90T, SP92TC, KM55, KM55R, KM55RC, KM56RC, KM85, KM85R, KM90R, KM94RC, KM100, KM100R, KM111R, KM130, KM130R, KM131, KM131R, KM235, KM235R, KMA80R, KMA120R, KMA130R, KMA135R, KMA200R, BT45

Recambio original para las siguientes máquinas STIHL:

FS55T | FS85T | FR85T | FR131T | SP90T | SP92TC-E | KM55 | KM55R | KM55RC-E | KM56RC-E | KM85 | KM85R | KM90 | KM90R | KM94RC-E | KM100 | KM100R | KM111R | KM130 | KM130R | KM131 | KM131R | KM235 | KM235R | KMA80.0R | KMA120.0R | KMA130R | KMA135R | KMA200.0R | BT45-Z

Tipo de máquina: Motor sistema combinado, Vareador, Ahoyador, Desbrozadora

Referencias OEM STIHL: 41407907501, 4140 790 7501, 4140-790-7501

Referencias alternativas STIHL: 41407907500, 4140 790 7500, 4140-790-7500

Denominaciones STIHL: Tornillo de muletilla, Palometa

Modelo de STIHL: FS 55 T, FS 85 T, FR 85 T, FR 131 T, SP 90 T, SP 92 TC-E, KM 55, KM 55 R, KM 55 RC-E, KM 56 RC-E, KM 85, KM 85 R, KM 90, KM 90 R, KM 94 RC-E, KM 100, KM 100 R, KM 111 R, KM 130, KM 130 R, KM 131, KM 131 R, KM 235, KM 235 R, KMA 80.0 R, KMA 120.0 R, KMA 130 R, KMA 135 R, KMA 200.0 R, BT 45-Z

Tipo de recambio: Original OEM

Fabricante: STIHL

Medidas: Rosca Ø 6,00 mm



