

STIHL - 61707642700 - Casquillo eje llanta rueda tractor cortacésped STIHL y VIKIN

RT4082.0, RT4082.1, RT4097.0SX, RT4097.1SX, RT5097.0, RT5097.0C, RT5097.0Z, RT5097.1, RT5097.1Z, RT5112.1Z, RT6112.0C, RT6112.0ZL, RT6112.1ZL, RT6127.0ZL, RT6127.1ZL, MR4082.0, MR4082.0K, MR4082.1

Recambio original para las siguientes máquinas STIHL:

RT4082.0 | RT4082.1 | RT4097.0SX | RT4097.1SX | RT5097.0 | RT5097.0C | RT5097.0Z | RT5097.1 | RT5097.1Z | RT5112.1Z | RT6112.0C | RT6112.0ZL | RT6112.1ZL | RT6127.0ZL | RT6127.1ZL | MR4082.0 | MR4082.0K | MR4082.1 | MR4082.2 | MT4097.0SX | MT4097.1SX | MT4112.0S | MT4112.1S | MT5097.0 | MT5097.0C | MT5097.0G | MT5097.0K | MT5097.0Z | MT5097.1 | MT5097.1C | MT5097.1Z | MT6112.0 | MT6112.0C | MT6112.0K | MT6112.0ZL | MT6112.1C | MT6112.1ZL | MT6127.0KL | MT6127.0ZL | MT6127.1ZL

Tipo de máquina: Tractor cortacésped, Rider

Referencias OEM STIHL: 61707642700, 6170 764 2700, 6170-764-2700

Referencias alternativas STIHL:

Denominaciones STIHL: Casquillo con valona

Modelo de STIHL: RT 4082.0, RT 4082.1, RT 4097.0 SX, RT 4097.1 SX, RT 5097.0, RT 5097.0 C, RT 5097.0 Z, RT 5097.1, RT 5097.1 Z, RT 5112.1 Z, RT 6112.0 C, RT 6112.0 ZL, RT 6112.1 ZL, RT 6127.0 ZL, RT 6127.1 ZL, MR 4082.0, MR 4082.0 K, MR 4082.1, MR 4082.2, MT 4097.0 SX, MT 4097.1 SX, MT 4112.0 S, MT 4112.1 S, MT 5097.0, MT 5097.0 C, MT 5097.0 G, MT 5097.0 K, MT 5097.0 Z, MT 5097.1, MT 5097.1 C, MT 5097.1 Z, MT 6112.0, MT 6112.0 C, MT 6112.0 K, MT 6112.0 ZL, MT 6112.1 C, MT 6112.1 ZL, MT 6127.0 KL, MT 6127.0 ZL, MT 6127.1 ZL

Tipo de recambio: Original OEM

Fabricante: STIHL

