

STIHL - 61657034805 - Corona eje dirección tractor cortacésped STIHL y VIKING

RT4097.0SX, RT4097.1SX, RT5097.0, RT5097.0C, RT5097.0Z, RT5097.1, RT5097.1Z, RT5112.1Z, RT6112.0C, RT6112.0ZL, RT6112.1ZL, RT6127.0ZL, RT6127.1ZL, MT4097.0SX, MT4112.0S, MT5097.1, MT5097.1C, MT5097.1Z

Recambio original para las siguientes máquinas STIHL y VIKING:

RT4097.0SX | RT4097.1SX | RT5097.0 | RT5097.0C | RT5097.0Z | RT5097.1 | RT5097.1Z | RT5112.1Z | RT6112.0C | RT6112.0ZL | RT6112.1ZL | RT6127.0ZL | RT6127.1ZL | MT4097.0SX | MT4097.1SX | MT4112.0S | MT4112.1S | MT5097.1 | MT5097.1C | MT5097.1Z | MT6112.1C | MT6112.1ZL | MT6127.1ZL

Tipo de máquina: Tractor cortacésped

Referencias OEM STIHL: 61657034805, 6165 703 4805, 6165-703-4805

Referencias alternativas STIHL: 61657034800, 6165 703 4800, 6165-703-4800

Denominaciones STIHL: Segmento de arandela dentada, Corona, Piñón

Modelo de STIHL y VIKING: RT 4097.0 SX, RT 4097.1 SX, RT 5097.0, RT 5097.0 C, RT 5097.0 Z, RT 5097.1, RT 5097.1 Z, RT 5112.1 Z, RT 6112.0 C, RT 6112.0 ZL, RT 6112.1 ZL, RT 6127.0 ZL, RT 6127.1 ZL, MT 4097.0 SX, MT 4097.1 SX, MT 4112.0 S, MT 4112.1 S, MT 5097.1, MT 5097.1 C, MT 5097.1 Z, MT 6112.1 C, MT 6112.1 ZL, MT 6127.1 ZL

Tipo de recambio: Original OEM

Fabricante: STIHL

